Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Providing and laying HDPE water line in Ganesh temple Block -1 JP Park Ward No 17
2	Administration Approval & Date	JC/RRN/AS/2245/13-14 Dtd 17-09-2013 by JC (RRN)
3	Technical Sanction Estimate No. & Date	CE/RRNZ/TS/ 292/13-14 Dtd:18/09/2013 by CE (RRN)
4	Estimate Amount	Rs.49.97 Lakhs
5	Job Code No.	017-14-000013
6	P-Code	P2201
7	Agreement No & date	EE/RRND/AG No./237/2013-14 Dtd.07-02-2014
8	Work order Number & Date	EE/RRND/W.O/237/2013-14 Dtd.07-02-2014
9	Contract Amount as per Agreement	Rs.53,46,303/-
10	Bill Amount	Rs.42,35,705/-
11	B.R. No. & Date	249/2014-15 dt. 30-06-2014
12	Agency	Shivakumar.K
13	M.B. Number & Page No. of Measurement recordes	119/2013-14 Pages to 11869 to 11874/2 [Xerox Copy of MB]
14	Date of Inspection	20/5/2016
15	Enclusures	1) Sketch Showing the Location of Site 2) 8 Number of photos taken during inspection of above site.
16	Inspection Report	The above site has been Inspected by me along with the concerned person-in-charge. It is observed that the Items indicated in the MB are not Subject to execution of work have been scrutinised and Inspected. It appears that the above work has been done. This has a reference to the Xerox Copy of MB No 119/2013-14

EE (RRND) RR Nagara

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 054

(R.Sathyanarayana)
20/5/2016
Inspection Report officer,

NAME OF WORK : PROVIDING AND LAYING HDPE WATER LINE IN GANESHA TEMPLE BLOCK-1 IN J.P. PARK WARD NO 17.



Asst. Executive Engineer
Yeshwanthpura Sub-Division
Bruhat Bangalore Mahanagara Palike

2015/2016

R. SATHYANARAYANA
INSPECTION OFFICER

Executive Engineer
Rajarajeshwari...
Bruh...

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿ
ಬೆಂಗಳೂರು-560 054

Providing and laying HDPE water line in Ganesha Temple block - 1 in J.P. Park ward no 17

Job no : 017-14-000013.

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

2/5/2016

R. SATHYANARAYANA
INSPECTOR